



MATS 550#1 - 1




Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58




MATS 550#1 - 2



Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58




MATS 550#1 - 3




Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58




MATS 550#1 - 4




Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58




MATS 550#1 - 5



Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58




MATS 550#1 - 6




Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58



MATS 550#1 - 7



Status	Time	%
Cycle ON	Total hours	25
Cycle OFF	Total hours	60
Setup	Total hours	10
Others	Total hours	5

Detailed - Top 4 Reasons for machine unavailable

Reason	Time	%	Reason	Time	%
NO OPERATOR	01:16	5,29	NO OPERATOR	01:16	5,29
TOOL MISSING	02:32	10,58	TOOL MISSING	02:32	10,58

